



CYPRES 2 Service Bulletin April 2008

Datum: 21.04.2008

Bulletin Nr.: C2 0408

Betrifft: Rückruf von CYPRES 2 Geräten

Status: verpflichtend

Betroffene Geräte:

CYPRES 2 aus dem Produktionszeitraum von 08.2006 - 10.2006.
Seriennummern zu finden auf Seite 2 und 3.

Hintergrund:

Anfang 2008 gab es zwei unberechtigte Aktivierungen in Australien, bei denen niemand zu Schaden kam. Beide Geräte wurden genau untersucht. Die Ergebnisse zeigen, dass die Auslösung in beiden Fällen durch einen fehlerhaften Sensor verursacht wurde. Da beide Geräte den 14 Tage dauernden Produktionsprozess ohne Anzeichen einer Unregelmäßigkeit durchlaufen haben, müssen wir annehmen, dass aus dieser Charge noch mehrere Geräte im Einsatz sind, die möglicherweise einen ähnlichen Sensorfehler aufweisen. Als Vorsichtsmaßnahme rufen wir alle eventuell betroffenen CYPRES 2 zurück, um vorsorglich den Sensor auszutauschen.

Maßnahme:

Bitte überprüfen ob Seriennummer in der Liste aufgeführt ist. Dafür braucht der Reservecontainer nicht geöffnet werden, die Seriennummer kann im Display aufgerufen werden (siehe CYPRES 2 Benutzerhandbuch).

Betroffene Geräte bitte zu Airtec schicken. Alle anfallenden Arbeiten am CYPRES werden kostenfrei durchgeführt, Rücksendung inbegriffen. Wir werden die Arbeiten so zügig wie möglich durchführen und legen jedem Gerät als Kostenanteilübernahme einen Verrechnungsscheck in Höhe von 50,- Euro bei. Ein Aufkleber am Gerät und ein Zertifikat bestätigen die Bearbeitung.

Wir möchten uns für hieraus entstehende Unannehmlichkeiten entschuldigen. Der Sicherheit wegen halten wir diesen Schritt aber für unumgänglich.

Wirksamkeit: mit Veröffentlichung / vor dem nächsten Sprung

Herausgegeben von:

Airtec GmbH & Co. KG Safety Systems

Helmut Cloth

Mittelstr. 69, 33181 Bad Wünnenberg, Deutschland

Tel: +49 2953 98990

Fax: +49 2953 1293

service@cypres.cc

Verteiler:

Alle Händler

Fallschirm- Magazine / Verbände

Parachute Industry Association

Expert

26798	26851	28157	28215	28332	28387	28440	28494
26799	26852	28158	28216	28333	28388	28441	28495
26800	26853	28159	28217	28334	28389	28442	28496
26801	26854	28160	28218	28335	28390	28443	28498
26802	26855	28161	28219	28336	28391	28444	28499
26803	26856	28162	28220	28337	28392	28445	28500
26804	26857	28163	28221	28338	28393	28446	28501
26805	26858	28164	28222	28339	28394	28447	28502
26806	26859	28165	28223	28340	28395	28448	28503
26807		28166	28224	28341	28396	28449	28504
26808	27148	28167	28225	28342	28397	28450	28505
26809	27149	28168	28226	28343	28398	28451	28506
26810	27150	28169	28227	28344	28399	28452	28507
26811	27151	28170	28228	28345	28400	28453	28508
26812	27152	28171	28229	28346	28401	28454	28509
26813	27153	28172	28230	28347	28402	28456	28510
26814	27154	28174	28231	28349	28403	28457	28511
26815	27155	28175	28232	28350	28404	28458	28512
26816	27156	28176	28233	28351	28405	28459	28513
26817	27157	28177	28234	28352	28406	28460	28514
26818	27158	28178	28235	28353	28407	28461	28515
26819	27159	28179	28236	28354	28408	28462	28516
26820	27160	28180	28237	28355	28409	28463	28517
26821	27161	28182	28238	28356	28410	28464	28709
26822	27162	28183	28239	28357	28411	28465	28710
26823	27163	28184	28240	28358	28412	28466	28711
26824	27164	28185	28241	28359	28413	28467	28712
26825	27165	28186	28242	28360	28414	28468	28713
26826	27166	28187	28243	28361	28415	28469	28715
26827	27167	28189	28244	28362	28416	28470	28716
26828	27168	28191	28245	28364	28417	28471	28717
26829	27169	28192	28246	28365	28418	28472	28718
26830	27170	28193	28247	28366	28419	28473	28719
26831	27172	28194	28248	28367	28420	28474	28720
26832	27173	28195	28249	28368	28421	28475	28721
26833	27174	28196	28250	28369	28422	28476	28722
26834	27175	28197	28251	28370	28423	28477	28723
26835	27176	28198	28252	28371	28424	28478	28724
26836	27177	28199	28253	28372	28425	28479	28725
26837	27178	28200	28254	28373	28426	28480	28726
26838	27179	28201	28255	28374	28427	28481	28727
26839		28203	28256	28375	28428	28482	28728
26840	28147	28204	28257	28376	28429	28483	28729
26841	28148	28205	28258	28377	28430	28484	28730
26842	28149	28206	28259	28378	28431	28485	28731
26843	28150	28207	28260	28379	28432	28486	28732
26844	28151	28208	28261	28380	28433	28487	28733
26845	28152	28209	28326	28381	28434	28488	28734
26846	28153	28210	28327	28382	28435	28489	28735
26847	28154	28211	28328	28383	28436	28490	28736
26848	28155	28212	28329	28384	28437	28491	28737
26849	28156	28213	28330	28385	28438	28492	28738
26850		28214	28331	28386	28439	28493	28739

Expert					Student	Tandem	
28740	28794	28940		29127			28284
28741	28795	28941		29128	27180	27212	28285
28742	28796	28942	29056	29129	27181	27213	28286
28743	28797	28943	29057	29130	27182	27214	28288
28744	28798	28944	29058	29131	27183	27215	28289
28745	28799	28945	29059	29132	27184	27216	28290
28746	28800	28946	29060	29133	27185	27217	28291
28747	28801	28947	29061	29134	27186	27218	28292
28749	28802	28948	29062	29135	27187	27219	
28750	28803	28949	29063	29136	27188	27221	
28751	28804	28950	29064	29137	27189	27222	29205
28752	28805	28951	29065	29138	27190	27223	29206
28753	28806	28952	29066	29139	27191	27224	29207
28754	28807	28953	29067		27192	27225	29208
28755	28808	28954	29068		27193	27226	29209
28756	28809	28955	29069	30091	27194	27227	29210
28757	28810	28956	29070	30093	27195	27228	29211
28758	28811	28957	29071	30094	27196	27229	29212
28759	28812	28958	29072	30095	27197	27230	29213
28760	28813	28959	29073	30097	27198	27231	29214
28761	28814	28960	29074	30098	27199	27232	29215
28762	28815	28961	29075	30099	27200	27233	29216
28763	28816	28962	29076	30100	27201	27234	29217
28764	28817	28963	29077	30101	27202	27235	29218
28765	28818	28964	29078	30103	27203	27236	
28766	28819	28965	29079	30104	27204	27237	
28767	28820	28966	29080	30106	27205	27238	
28768	28821	28967	29081	30107	27206	27239	
28769	28822	28968	29082	30108	27207	27240	
28770	28824	28969	29083	30110	27208	27241	
28771	28825	28970	29084	30111	27209	27242	
28772	28826	28971	29085	30112	27210		
28773	28827	28972	29086	30113	27211		
28774	28828	28973	29087	30114		28262	
28775	28829	28974	29108	30115		28264	
28776	28830	28975	29109	30116	28901	28265	
28777	28831	28976	29110	30117	28902	28266	
28778	28832	28977	29111	30118	28903	28267	
28779	28833	28978	29112	30119	28904	28268	
28780	28834	28979	29113	30120	28905	28269	
28781	28835	28980	29114	30121	28907	28270	
28782	28836	28981	29115		28908	28272	
28783	28929	28982	29116		28909	28273	
28784	28930	28983	29117		28910	28274	
28785	28931	28984	29118		28911	28275	
28786	28932	28985	29119		28912	28276	
28787	28933	28986	29120		28913	28277	
28788	28934	28987	29121		28914	28278	
28789	28935	28988	29122		28915	28279	
28790	28936	28989	29123		28916	28280	
28791	28937	28990	29124		28917	28281	
28792	28938	28991	29125		28918	28282	
28793	28939	28992	29126		28919	28283	

Speed
29172

TECHNICAL & SAFETY COMMITTEE

INTERNATIONAL PARACHUTING COMMISSION (FAI)



Technical & Safety Information Notice No.	2/2008	W.N. 15
Date of Issue	21 April 2008	
Subject Matter	<p>Cypres 2 AAD</p> <p>Airtec Safety Systems - Service Bulletin, April 2008 Airtec Bulletin Number – C2 0408, issued 21.04.08</p> <p>Concerning – Cypres 2 units from production period August 2006 to December 2006. Note – this is a corrected Information Notice; an earlier version gave an incorrect time-frame (which had been supplied by Airtec) as August to October 2006.</p> <p>Units in question are:- 667 Expert, 50 Student, 72 Tandem, 1 Speed. A listing of the serial numbers of the units effected is to be found in the Airtec bulletin, C2 0408, which is appended to this Information Notice. The serial numbers which appear in the Airtec Bulletin remain correct.</p> <p>Background – The following is Airtec’s statement:- ‘Earlier this year we experienced two unwanted activations in Australia. Nobody was hurt. Both units have been examined extensively at Airtec, with the finding that a defective sensor caused the activation in both cases. As both units passed the more than 14 days period manufacturing testing process without any noticeable problems, we must assume that it is possible that there are more units of this production batch in use with a similar sensor defect. As a precaution, we have decided to recall all potentially affected CYPRES 2 units for a preventive sensor replacement.</p> <p>Status of Bulletin – Airtec declared the status of their Bulletin to be <u>Mandatory</u></p> <p>Airtec Service Bulletin direction – ‘Please compare the serial number of each CYPRES 2 with the attached list. Note that it is not necessary to open the reserve container, as it is easy to check the CYPRES 2 serial number on the display. (See your CYPRES 2 User Guide for more info.) In case your unit is effected, please forward it to Airtec – Germany, or to SSK Industries in the US. All necessary work will be done as quickly as possible and free of charge, including return shipment. As compensation Airtec will include a cheque in the amount of \$70.00 US for each affected unit upon its return.</p>	

	<p>Treated units will wear a sticker and have a certification. We apologise for the inconvenience this may cause, however we feel it is necessary to ensure your safety.'</p> <p>Compliance date - Effective immediately, before the next jump.</p> <p>US shipping address: SSK Industries Inc., 1008 Monroe Road, Lebanon, OH 45036. Tel – 513-934-3201 service@CYPRES-USA.com</p>
Authority	<p>Airtec GmbH & Co. KG Safety Systems Helmut Cloth Tel : +49 2953 98990 Fax : +49 2953 1293 service@cypres.cc Mittelstrasse 69 33181 Bad Wünnenberg Germany</p>

Technical and Safety Information Notices issued by the Technical & Safety Committee of the International Parachuting Commission (FAI) are issued as information and help to parachuting nations and their affiliated members. The Information Notices are of an objective informative nature and there is no direct or implied criticism of any manufacturer or product intended. The Information Notices do not claim to be complete.

The Information Notices may result from:-

- 1 An incident or experience in the field being reported.**
- 2 The issue of a notice by a manufacturer or by a National Parachuting Organisation. In the case of equipment being the subject of the bulletin the reader is advised to check with the manufacturer regarding the current status or position of that equipment.**

Technical & Safety Committee of IPC, IPC and FAI accept no liability for the use or misuse of any information contained in this Information Notice. The reader assumes all liability.

The Technical & Safety Committee, International Parachuting Commission, can be contacted on e-mail - lmcnulty@skydiveireland.ie

**Liam McNulty, Technical & Safety Committee, International Parachuting Commission.
21 April 2008.**