



## ÖSTERREICHISCHER AERO-CLUB

SEKTION FAA Blattgasse 6, A-1030 WIEN

Sicherheitsmitteilung  
SM171001

**Datum:** 03.10.2017

**Bezug:** SIFE SB 2017-002


**Betroffene Muster:** SIFE Hauptschirmtragegurte

**Status:** verpflichtend, vorm nächsten Sprung

**Grund:** Meldung, dass bei einem Release Funktionstest am Haupttragegurt, die Funktion erst nach händischem Lösen der 3-Ringe gegeben war. Die Herstelleruntersuchung ergab, dass der betroffene Haupttragegurt nicht den Herstellerspezifikationen entsprach

**Maßnahme:**

1. Kontrolliere ob die Haupttragegurte, den auf der Abbildung gezeigten Toleranzen entspricht:
2. Sollten die Tragegurte nicht der Herstellerspezifikation entsprechen, oder sollten Unklarheiten auftreten, ist der Hersteller unter: [office@sife.at](mailto:office@sife.at) zu kontaktieren.  
Betroffene Haupttragegurte werden durch den Hersteller kostenfrei ersetzt.



**SIFE**  
**Hauptstrasse 126**  
**8740 Zeltweg**  
**office@sife.at**  
**0043 699 181 00 656**

**Verteiler:** Systembetreuer, Vereine/Clubs/Schulen, Sektionsleiter, Händler,

FAA Österreichischer Aeroclub

  
HRIBERNIK Michael,  
OeAC-FS-4859



Diana Duschek  
Hauptstrasse 126  
A-8740 Zeltweg

UID: ATU68019459  
+43 699 18100656  
[www.sife.at](http://www.sife.at)

## Service Bulletin 2017-002

Issue Date: October 2, 2017

Issue Number: 2017-002

Subject: Ring position on SIFE main risers

**Status: mandatory before the next jump**

Background:

We have been informed that during the simulation of a cutaway procedure, the 3-ring-system released only after a short tug on the risers. The result of our investigations is that the position of the small ring on the affected main risers may not meet the design specifications.




Diana Duschek  
Hauptstrasse 126  
A-8740 Zeltweg

UID: ATU68019459  
+43 699 18100656  
[www.sife.at](http://www.sife.at)

**Procedures to be followed:**

1. Check the ring position on your main risers with the following figure:



2. If your main risers do not meet the design specifications, or if you are unsure please send us an e-mail to [office@sife.at](mailto:office@sife.at).

The main riser replacement will be free of charge.

We apologize to all customers who are affected by this service bulletin.

Please contact SIFE for any further information:

**SIFE**  
**Hauptstrasse 126**  
**8740 Zeltweg**  
**[office@sife.at](mailto:office@sife.at)**  
**0043 699 181 00 656**

Authorised Signatory

Diana Duschek  
Head of Design  
[office@sife.at](mailto:office@sife.at)  
+43 699 181 00 656

Distribution

Austro Control  
Aeroclub  
SIFE Dealers  
Direct Customers