



**AAD sa/nv**  
Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)

## **Product Service Bulletin**

**Issue Date:** 02/21/2007

**Bulletin Number:** *PSB-3*

**Subject:** Vigil Cutters with Plastic Insert

**Status:** Advisory

### **Identification:**

Vigil AAD, All Cutters with Plastic Insert made before August 2006.  
Part Number: 9582006 Made Before August 2006

### **Background:**

Cutters have been found in the field with damaged plastic inserts that have in turn damaged the closing loops. If the damage is severe enough, it is possible for the reserve-closing loop to sustain damage.

In regards of the FFP Bulletin #122:

Until now all the reported damaged cutters with plastic insert have been identified, recalled and replaced.



**AAD sa/nv**  
Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)

### **Service Bulletin:**

Inspect the plastic insert for signs of damage. At the same time inspect the loop for signs of wear and damage from the cutter frame.

If damage is found, please contact your dealer, Vigil AAD Brussels or Vigil USA for advice and/or eventual cutter replacement.

### **Compliance Date:**

Next repack cycle.

### **Authority:**

Yann Bronnec / Jo Smolders  
P.R. Manager / President

**AAD sa/nv**  
Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [yann@vigil.aero](mailto:yann@vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)

**Vigil USA LLC**  
1645 Lexington Avenue  
Deland, FL 32724  
+386 736 8464 – Fax : +386 736 8468  
[www.vigil.aero](http://www.vigil.aero) - [candace@vigil.aero](mailto:candace@vigil.aero)



**AAD sa/nv**  
Bld A.Reyers, 193  
1030 Brussels – Belgium – Europe  
+32 2 732 65 52 – Fax : +32 2 736 06 27  
[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)



**OK**



**OK**



**OK**



**NOT OK**



**NOT OK**



**NOT OK**



**AAD sa/nv**

Bld A.Reyers, 193

1030 Brussels – Belgium – Europe

+32 2 732 65 52 – Fax : +32 2 736 06 27

[www.vigil.aero](http://www.vigil.aero) - [info@vigil.aero](mailto:info@vigil.aero)



### **New Full Inox Replacement Cutter (From August 2006)**

#### **The Distribution list shall include but is not limited to:**

- All registered owners.
- All AAD dealers.
- Manufacturers
- Parachute Industry Association.
- All Parachuting publications.
- All National Aero Clubs, Parachuting Section.
- IPC Technical Committee.
- Military Parachute Organizations.



**Superior Technology  
That's cost effective**

**Choice of Champions**

**Safety - Quality - Innovation - [www.vigil.aero](http://www.vigil.aero)**

