

## SERVICE BULLETIN no. 03/01/2014

Extension of basic lifetime of sport parachutes parts over 15 years – specification of conditions

- **1. CONCERNS:** Parachute containers OP-087 and OP-093/01 with harnesses and parts (Ripcord Handle Reserve, Three Ring Release Ripcord) by sport parachutes produced by company MarS spol. s r.o. or MarS a.s., used in civilian air sector.
- **2. REASON:** Possibility of extension of basic lifetime of parts in point 1 over the given basic lifetime.

## 3. PROCEEDING: Basic lifetime of parts in point 1 is 15 years from the production date under condition that instructions stated in Technical description are followed.

User will send parts including Technical certificate of the parachute container with the harness with correct and full user's records (of all checks, repairs) to the producer for checking before the basic lifetime of 15 years is terminated.

Producer will carry out a detailed check of individual parts and on the basis of their physical condition the producer decides about extension or non-extension of their basic lifetime over 15 years.

In case of successful check the producer will extend the basic lifetime – maximum by 2 years.

Interval of lifetime extension is counted always from the date of basic lifetime termination.

Producer make a note in the Technical certificate about the carried out check and in case of successful check also a note of lifetime extension, or a note of repair.

With parts in excellent condition, it is possible to extend the lifetime repeatedly.

Further lifetime extension in case of successful check is possible in the length of maximum 2 years starting the date of the extended lifetime termination.

It is possible to repeat such proceedings with well-preserved parts but only until the complete lifetime of 20 years.

If the user does not present parts before its lifetime runs out, it will only be extended until the lifetime extension date in the immediate future. From the production date.



С

## WARNING:

During the time, when the parts do not have extended lifetime, the producer does not guarantee their function and in case of exceptional situation the producer does not have responsibility for possible damage on health or property.

**4. VALIDITY:** From date of bulleting issue. By issuing of this Service Bulletin, the validity of Service Bulletin no. 12/12/2010 from 15.12.2010 is cancelled and this Service Bulletin contributes to facts of Service Bulletin no. 1/01/2003 from 10.01.2003 in point 2 C about possibility of extension of basic lifetime.

5. DATE OF ISSUE: In Jevíčko, on 24.01.2014

Ing. Jaroslav Sedlák – Technical Department Manager MarS a.s.

Stamp and signature:

Mar a.s Okružní II 239, Jeviči www.marsjev.cz mars@marsjev.cz DIC: 265 - 48152365